



Job Name: _____

Job Location: _____

Contractor: _____

Engineer: _____

Approval: _____

Replacement Ballcock Kit to fit Kohler Rialto

Design Features:

- Plastic Construction
- Replaces Kohler OEM #84499
- Imported

Kit Includes:

- Fill Valve (1)
- Float (1)
- Refill Tubing (1)
- 8-3/4" Ballcock Rod (1)
- Caps (1)



Material Specifications	
Part	Material
Fill Valve	White Plastic
Float	Black Plastic
Ballcock Rod	Brass
Cap	Black Plastic
Refill Tube	Clear Plastic
Washers and Seals	Black Rubber



W-R#	Description	Type	Weight
1305500	Ballcock to fit Kohler Rialto	3-Screw	1.19 lbs.
1304532	Ballcock Top Assembly 1B1X (Rialto)	3-Screw	.105 lbs.
1304506	Ballcock Plunger Repair Kit 1B1X (Rialto)	3-Screw	.055 lbs.
1322002	Replacement 4" Plastic Float Only		.130 lbs.
2721002	Replacement Shank Washer Only		.029 lbs.